Alabama Department of Public Health

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPLE CONSTRUCTION	(X3) DATE SURVEY COMPLETED
	N5805	A. BUILDING: **01 - BUILDING 0101** B. WING _____	**02/21/2024**

NAME OF PROVIDER OR SUPPLIER	STREET ADDRESS, CITY, STATE, ZIP CODE
COL ROBERT L HOWARD STATE VETERANS HOME	**7054 VETERANS PARKWAY** **PELL CITY, AL 35125**

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
L 000	Initial Comments . Regulation 22-21-20, et. seq., Code of Alabama, amended July 30, 2016 Rule 420-5-10, Nursing Facilities K3 Building: 0101 K6 Plan Approval: 06/07/2011 K7 Survey Under: 2012 Existing K8 SNF Locking Devices: Delayed Egress 30 sec.w/Wander Guard (Has approval letter from ADPH) Generators: Three Diesel, Generac 400 kW in tandem (installed 2011 w/remote manual stop stations) FACP: Notifier by Honeywell (installed 2011) Smoke Detection: Complete Beds: 174 Census: 169 Type of Structure: Per architect's plans and construction type matrix this building is a single story protected noncombustible, Type II (111) with heavy timbers (HT) (glue laminated timber) at roof construction/ceiling. The facility has a complete automatic sprinkler system. The following corridor doors in Bldg. Four do not have not positive latching hardware: Eagles Landing room 4211, Chapel room 4204, Library room 4205, Beauty Salon room 4208, Barber Shop room 4209, Stars & Stripes Cafe room 4210 in accordance with 2000 NFPA 101, 18.3.6.1, exception Number 1: smoke detectors in each room. On the date of this licensure survey, the facility was found to be in compliance with 420-5-10 and with the applicable provisions of the 2012 NFPA	L 000		

Health Care Facilities
LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE TITLE (X6) DATE

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPLE CONSTRUCTION	(X3) DATE SURVEY COMPLETED
	N5805	A. BUILDING: **01 - BUILDING 0101** B. WING _____	**02/21/2024**

NAME OF PROVIDER OR SUPPLIER	STREET ADDRESS, CITY, STATE, ZIP CODE
COL ROBERT L HOWARD STATE VETERANS HOME	**7054 VETERANS PARKWAY** **PELL CITY, AL 35125**

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
L 000	Continued From page 1 101 Life Safety Code (LSC), the 2012 NFPA 99 Health Care Facilities Code and the standards referenced by these codes, as observed by the LSC Surveyors while accompanied by the facility maintenance personnel.	L 000		